

Errata to ASCE/SEI 31-03

Seismic Evaluation of Existing Buildings

Updated 4-11-06

The following typographical errors are contained in the 2003 edition of ASCE/SEI 31-03. This list will be periodically updated as warranted.

Chapter 4, p. 4-28

Table 4-5: "m-factors for Steel Components"

Under Fully restrained Moment Frames - columns

"Py" is undefined

Py is the compressive axial strength of the column